

ISS Palumbo

Oil Spill Simulation Aghula 1 – April 14th, 2014

www.iss-palumbo.com
A World of Local Expertise

Integrated project and marine logistic solutions





Date: April 14th, 2014

Location: Aghula 1

Time: 10:00LT

 On April 14th, AM during Fuel transfer from the Supply Vessel Sea Tortuga to Saipem 10 000 it was noticed that a pipe had burst and approximately 100 x 100 m area was polluted with Marine Gas Oil.







 The Security Offshore Manager immediately informed the Security Vessels Bateleur and Raptor.





A World of Local Expertise






- The two vessels immediately proceeded to the after section of Saipem 10000.
- Raptor had the Emergency Oil Pollution kit ready and on standby.
- Both vessels started their Fire monitors and started breaking up the fuel.
- Raptor asked permission to proceed within the 500 m exclusion zone to use there propeller wash to increase the breakup of fuel.





- Saipem 10000 informed Authorities of the spill, while both security vessels kept moving with the fuel sleek, spraying with fire monitors.
- At 12:20 PM fuel sleek was not visible anymore and both vessels were instructed to move 2 to 4 NM SE of Saipem 10000 to ensure that no fuel sleeks escaped.
- Nothing was found and security vessels proceeded back to their respective patrolling sites.

A World of Local Expertise



Thank you

www.lss-palumbo.com
A World of Local Expertise